


MS Coat ONE

CLINICAL PROCEDURE

Clean the tooth surface




Saturate Felt Applicator with MS Coat ONE



Gently rub the tooth surface with the Applicator. For best results, rub the surface for more than 30 seconds.

If the surface remains painful, you can repeat the treatment (rub with the saturated applicator and air-dry) 2 or 3 times at the same appointment.



Dry with air-syringe

Rinse

Completed

